




R- 11001 A

- DO NOT USE ANY TYPE OF BLEACH OR STAIN REMOVING CHEMICALS
- DO NOT OVER EXPOSE DAMP FABRIC TO STRONG SUNLIGHT
- IRON AT MODERATE TEMPERATURE








R- 11001 B

- DO NOT USE ANY TYPE OF BLEACH OR STAIN REMOVING CHEMICALS
- DO NOT OVER EXPOSE DAMP FABRIC TO STRONG SUNLIGHT
- IRON AT MODERATE TEMPERATURE







R- 11001

- DO NOT USE ANY TYPE OF BLEACH OR STAIN REMOVING CHEMICALS
- DO NOT OVER EXPOSE DAMP FABRIC TO STRONG SUNLIGHT
- IRON AT MODERATE TEMPERATURE







R- 11001 C

- DO NOT USE ANY TYPE OF BLEACH OR STAIN REMOVING CHEMICALS
- DO NOT OVER EXPOSE DAMP FABRIC TO STRONG SUNLIGHT
- IRON AT MODERATE TEMPERATURE

